TASK NAME	RESPONSIBLE	Date	1	Sep-15 8 15 22 29	ct-15 3 20 27	Nov-15 3 10 17 24	Dec-15 15 22 29	Jan-16		eb-16 9 16 23	3 1	Mar- 8 15		Apr-16 12 19	May-16 3 10
General System Design	All	September 4, 2015					 		 _						
Stator Design Research Winding Types Pole and Slot Pitch Pole Depth	Tim Mason All	November 17, 2015 September 22, 2015 September 22, 2015 November 17, 2015													
Slot/Teeth Ratio Number of Coil Windings	All All	October 27, 2015 November 17, 2015													
Purchasing	All	November 30, 2015													
Construction Coil Windings Stator Mount Microcontroller Sytem VFD Programming Sensor Programming	Mason and Tim Mason and Tim Tyler Tyler Tyler Tyler	February 2, 2016 January 25, 2016 February 8, 2016 February 8, 2016 February 8, 2016 January 25, 2016													
Implementation	All	February 9, 2016													
Testing	All	March 7, 2016										9	5%		
Deliverables Project Proposal - Oral Presentation Project Proposal - Written Webpage Release Fall Progress Presentation Fall Performance Evaluation Fall Performance Review Design Review Final Report Draft Oral Presentation Preparation Final Project Oral Presentation Poster Presentation to IAB Final Project Report Project Website Verification	AII AII AII AII AII AII AII AII AII AII	October 1, 2015 October 15, 2015 October 28, 2015 November 19, 2015 November 19, 2015 December 3, 2015 March 1, 2016 April 12, 2016 April 21, 2016 April 29, 2016 May 3, 2016 May 3, 2016													

The LIM team took the wheel off of the system to perform additional testing of the LIM to determine why force was not being produced. The team decided to disconnect the VFD and connect a DC power supply to the LIM. The DC power supply was used to energize the coils to produce a magnetism to allow for the group to determine the polarity of each coil. The DC power supply was set-up to output a current of 3 [A], as the group designed the stator to operate at 3 [A]. The group then took a screw to each stator tooth to see if the coils were magnetized. The screw was attracted to each stator tooth proving that the stator teeth were indeed producing a magnetic field. Mason and Tyler then went and purchased a compass in order to determine which teeth were a North or South pole. Moving the energized stator coils Tyler and Mason determined that one of the coils was connected incorrectly (was a North and not a South pole). Switching the polarity of the coil the group then was able to reattach the simulated linear track and the VFD.

The small change allowed for the LIM to rotate the simulated linear track. The wheel needed a small push in order to overcome the static friction force. Operating the VFD at 60 [Hz] the LIM provided a constant force to the wheel allowing it to continually rotate. The speed achieved at 60 [Hz] was not as originally expected, thus showing the inefficient nature of a LIM. It was determined that the majority of the inefficiencies were due to the simulated linear track. The copper track of the simulated linear track had no steel backing, therefore creating more flux leakage losses into the plastic of the wheel. The group added steel backing behind a portion of the copper track to test if the speed would be increased. It was determined that as the wheel rotated and the metal backing portion of the wheel rotated toward the LIM the wheel would increase in speed and then slow down when the metal backing was no longer by the stator.

Industrial Advisory Board Poster Presentation took place on 4/29/16.

Future work before the LIM team graduates would be to take the copper track off of the wheel and add a steel backing behind the copper track and test the wheel once again to see if maximum designed speed can be reached (1,200 [rpm]). The thicker the steel backing the less losses due to flux leakage will occur. The group designed the mounting solution to allow for the wheel to be moved up and down in order to allow for backing to be added to the copper track.